

PALIER COTE GAUCHE LAVE LINGE BRANDT THOMSON VEDETTE

Referens: 51X2877



BESKRIVNING

Kit palier tambour lave linge Brandt Thomson Vedette

Référence connue: 51x2877

Se monte sur les appareils suivant:

- 1086VE - 1086VE (VEDETTE),
- 1163 - 1163 (DE DIETRICH),
- BT1288 - 7YF8BRHKA (BRANDT),
- BX1088 - 7S37BRSGA (BRANDT),
- BX1089 - 7QF8BRHKA (BRANDT),
- CT100 - 7YF8THFFE (THOMSON),
- CT110 - 7YF8THFFF (THOMSON),
- CTS115 - 7YF8THFFG (THOMSON),
- EL2000 - 7R53THFFA (THOMSON),
- EL3000 - 7R57THFFA (THOMSON),

- ELS3000 - 7X57THFFA (THOMSON),
- F10LS - 7YF8FOEEA (FAGOR),
- LBS1000 - 7S57THIIA (THOMSON),
- LD0405F1 - LD0405F11 (DE DIETRICH),
- LD0415F12 - LD0415F12 (DE DIETRICH),
- LD0485F1 - LD0485F11 (DE DIETRICH),
- LDO405F11 - LDO405F11 (DE DIETRICH),
- LS1100 - 7QF8THCHA (THOMSON),
- LS113V - 7QF8THFFA (THOMSON),
- LS113VX - 7QF8THEXA (THOMSON),
- LS113VXE - 7QF8THEXC (THOMSON),
- LS210 - 7Q57THEEA (THOMSON),
- LS215 - 7QF8THEEA (THOMSON),
- LSB120 - 7S57BREEA (BRANDT),
- LST1100 - 7Y57THEEA (THOMSON),
- LSV19 - 0116229D (BRANDT),
- LSV20 - 7QF8BRFFA (BRANDT),
- LSV30 - 7YF8BRFFA (BRANDT),
- S390 - 7S57BRFFA (BRANDT),
- SOLEIL - 7YF8THEEB (THOMSON),
- SOLEIL10 - SOLEIL10 (THOMSON),
- SOLEIL100 - 7YF8THFFA (THOMSON),
- SOLEIL10X - 7YF8THEXE (THOMSON),
- SOLEIL110 - 7YF8THFFB (THOMSON),
- SOLEIL50 - 7Y57THFFA (THOMSON),
- SOLEIL50B - 7Y57THFFB (THOMSON),
- SOLEIL80 - 7Z57THFFA (THOMSON),
- SOLEIL90 - 7YF8THFFC (THOMSON),
- TS1001 - 7S47THCHA (THOMSON),
- TX168 - 7S37THSGA (THOMSON),
- TX169 - 7S37THSGB (THOMSON),
- TX178 - 7S57THSGA (THOMSON),
- TX178N - 7QF8THSGA (THOMSON),
- TX179 - 7S57THSGB (THOMSON),
- WA1024 - 7F27THDDA (THOMSON),
- WA904 - 7F23THDDB (THOMSON),
- WA904W - 7F23THDDD (THOMSON),
- WA924 - 7F23THDDA (THOMSON)

FICHE TECHNIQUE

Varumärke	THOMSON
EAN13	3663216017643